

mainSwitch

		2026-1				2026-2				2026-3				2026-4				2026-5				2026-6					
		2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	
Hardware																											
mainSwitch																											
PCB routing problem																											
Switch via photodiode																											
Power supply on CANBus is very poor																											
Wakeup-Button is not working																											
Verseion 2: more power, RTC																											
LM25056: Current calculated wrongly																											