

Minutnik

					2026-1					2026-2					2026-3					2026-4					2026-5					2026-6				
					2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26					
Hardware																																		
Minutnik																																		
Buttons do not fit																																		
Minutnik elnk																																		
Does UART-RX need Pullu por -down?																																		
Minutnik elnk - v0.2.x																																		
consumption tests completely (...)																																		
Yellow and red LEDs are quite (...)																																		
Power consumption too high																																		
Are both wakeups working correctly																																		